FIRE SUPPRESSION SYSTEMS

^{*} Re-inspection plan review- \$100.00

Maintenance / Repair Fee: \$0.00			
No Fee	No Plan Review	AHJ	
No Fee	No Permit	IFC- 105.1.5	
No Fee	No Inspection	AHJ	
	Service Tag REQUIRED	IFC - 901.6.3 Records	

Modification/Upgrade Fee: \$150.00			
\$50.00	Plan Review / As Built Review REQUIRED	IFC 901.2	
\$50.00	Permit REQUIRED***	IFC- 105.1.1; 105.7; 105.7.1	
\$50.00	Inspection REQUIRED** - NO TRIP TEST	IFC- 107.2; 904.4	
	Updated Certificate of Installation Tag REQUIRED	IFC 901.6.3	

NEW Installation: \$200.00			
\$100.00	Plan Review REQUIRED*	IFC 901.2	
\$50.00	Permit REQUIRED***	IFC - 105.1.1; 105.7; 105.7.1	
\$50.00	Inspection REQUIRED** and Trip Test REQUIRED** - This is a pass / fail inspection	IFC- 107.2; 904.4	
	Installation Label REQUIRED	IFC 901.6.3	
	Certificate of Installation REQUIRED	IFC 901.6.3	

^{**}Re-inspection fee - \$50.00

^{***}Working without permit- 1.5X permit fee and a citation $\underline{\textbf{WILL}}$ be issued.